



Notes:

1. D2-D7: 2KV, fast recovery type.
2. C6-C8, C10: 1nF, all 3KV.
3. C11-C13: 1nF, C9: 47pF, all 6KV.
4. Transformer winding specs estimated and may be off by +/-25 percent.

## Inverter HeNe PSU Using IC (IC-HI1)

Drawn by: Samuel M. Goldwasser

sam@repairfaq.org

Title

Inverter HeNe Laser PSU Using IC (IC-HI1)

Size Document Number

A IC-HI1-SCH

REV

1.4

Date: April 20, 2003 Sheet 1 of 1